

MSP430F20xx Device Erratasheet


Current Version

Devices	Rev:	BCL9	BCL10	BCL11	CPU4	FLASH16	FLASH22	PORT10	SDA3	TA12	TA16	US14
MSP430F2001	C	✓	✓	✓	✓	✓	✓	✓		✓	✓	
MSP430F2011	C	✓	✓	✓	✓	✓	✓	✓		✓	✓	
MSP430F2002	C	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓
MSP430F2012	C	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓
MSP430F2003	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F2013	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓

Note: See Appendix for prior revisions


Package Markings

PW14: TSSOP(PW) 14-pin




YM = Year and Month Date Code
 LLLL = LOT Trace Code
 S = Assembly Site Code
 # = DIE Revision
 o = PIN 1

RSA16: QFN(RSA) 16-pin



YM = Year and Month Date Code
 LLLL = LOT Trace Code
 S = Assembly Site Code
 # = DIE Revision
 o = PIN 1

N14: PDIP(N) 14-pin



YM = Year and Month Date Code
 LLLL = LOT Trace Code
 S = Assembly Site Code
 # = DIE Revision

Detailed Bug Description

BCL9 BCL9 – Bug description

Module: BasicClock, Function: ACLK divider modifications require delay before entering LPM3

After modifying the DIVAx bits, immediately entering LPM3 can cause the modification to be ignored and the divider settings not to take effect. Reading back the DIVAx bits will indicate the intended setting even when the divider has not been correctly applied.

Workaround:

When the DIVAx bits are modified, a delay of one complete ACLK (VLO or LFXT1CLK) period must elapse before entering LPM3. The delay is only necessary the first time LPM3 is entered after the DIVAx bits are modified. After the one-period delay, LPM3 may be entered and exited normally without additional delays.

BCL10 BCL10 – Bug description

Module: BasicClock, Function: MCLK = ACLK and P2SEL control bits

When using ACLK as the CPU MCLK clock source, the oscillator failsafe feature does not automatically switch MCLK to the DCO if the P2SEL6 or P2SEL7 bits are cleared. This applies when ACLK = LFXT1 (e.g. external low frequency clock source). The CPU will halt operation since no MCLK signal is present.

Workaround:

None

BCL11 BCL11 – Bug description

Module: BasicClock, Function: Watchdog failsafe when using ACLK

When using ACLK as the WDT+ clock source, the WDT+ oscillator failsafe feature does not automatically switch to the DCO if the P2SEL6 or P2SEL7 bits are cleared. This applies when ACLK = LFXT1 (e.g. external low frequency clock source). The WDT+ will halt operation since no clock signal is present.

Workaround:

None

CPU4 CPU4 - Bug description:

Module: CPU, Function: PUSH #4, PUSH #8

The single operand instruction PUSH cannot use the internal constants (CG) 4 and 8. The other internal constants (0, 1, 2, -1) can be used. The Assembler version 1.08 and higher produces correct code. The number of clock cycles is different:

PUSH #CG uses address mode 00, requiring 3 cycles, 1 word instruction

PUSH #4/#8 uses address mode 11, requiring 5 cycles, 2 word instruction

Workaround implemented in assembler.

No fix planned.

Detailed Bug Description (continued)

FLASH16 FLASH16 - Bug description:

Module: Flash, Function: Modifying INFOA addresses when LOCKA = 1 will modify main flash memory

When attempting to write to an address location, or perform a segment erase of INFOA while the LOCKA bit is set, flash memory beginning at main memory location 0xF040 and extending for 64 bytes to address 0xF07F will be modified erroneously. These 64 bytes are addressed and modified in place of the INFOA addresses when writes or erases are performed within the INFOA address space AND LOCKA = 1.

Workaround:

Prior to modifying (writing or erasing) any address within the INFOA Flash memory segment, properly clear the LOCKA control bit as described in the MSP430x2xx User's Guide to unlock the segment. Once the modification is complete, setting the LOCKA bit is recommended.

FLASH22 FLASH22 – Bug description

Module: Flash, Function: Flash controller may prevent correct LPM entry

When ACLK (or SMCLK) is used as the Flash controller clock source, and this clock source gets deactivated due to a low-power mode entry while a Flash erase or write operation is pending, the Flash controller will keep ACLK (or SMCLK) active even after the Flash operation has been completed. This will result in an incorrect LPM entry and increased current consumption. Note that this issue can only occur when the Flash operation and the low-power mode entry are initiated from code located in RAM.

Workaround:

Do not enter low-power modes while Flash erase or write operations are active. Wait for the operation to be completed before entering a low-power mode.

PORT10 Port10 - Bug description:

Module: Digital I/O, Function: Pull-up/down resistor selection when module pin function is selected

When the pull-up/down resistor for a certain port pin is enabled (PxREN.y=1) and the module port pin function is selected (PxSEL.y=1), the pull-up/down resistor configuration of this pin is controlled by the respective module output signal (Module X OUT) instead of the port output register (PxOUT.y).

Workaround:

None. Do not set PxSEL.y and PxREN.y at the same time.

SDA3 SDA3 - Bug description:

Module: SD16_A, the interrupt delay function can result in incorrect conversion data

The interrupt delay operation can result in incorrect conversion data when SD16INTDLYx = 01, 10 or 11.

Workaround:

Use SD16INTDLYx = 00 setting (Interrupt generated after 4th conversion). This will apply to the first conversion in Continuous mode and to each conversion in Single mode.

Detailed Bug Description (continued)

TA12 TA12 - Bug description:

Module: TimerA, Function: Interrupt is lost (slow ACLK)

TimerA counter is running with slow clock (external TACLK or ACLK) compared to MCLK. The compare mode is selected for the capture/compare channel and the CCRx register is incremented by 1 with the occurring compare interrupt (if TAR = CCRx).

Due to the fast MCLK the CCRx register increment ($CCRx = CCRx + 1$) happens before the TimerA counter has incremented again. Therefore the next compare interrupt should happen at once with the next TimerA counter increment (if $TAR = CCRx + 1$). This interrupt gets lost.

Workaround:

Switch capture/compare mode to capture mode before the CCRx register increment. Switch back to compare mode afterwards.

TA16 TA16 - Bug description:

Module: TimerA, Function: First increment of TAR erroneous when IDx > 00

The first increment of TAR after any timer clear event (POR/TACLR) happens immediately following the first positive edge of the selected clock source (INCLK, SMCLK, ACLK or TACLK). This is independent of the clock input divider settings (ID0, ID1). All following TAR increments are performed correctly with the selected IDx settings.

Workaround:

None

USI4 USI4 - Bug description:

Module: USI, Function: I2C Slave mode can generate a glitch at SCL

USI I2C Slave Operation at slower communication rates < 20kbps. During I2C Bus Active operation, if USICNT is written while SCL is high, I2C module will generate a glitch on SCL that can corrupt the I2C bus sequence.

Workaround:

Verify that SCL is low before writing USICNT register.

Appendix: Prior Versions

Devices	Rev:	BCL9	BCL10	BCL11	CPU4	FLASH16	FLASH22	PORT10	SBW1	SDA2	SDA3	TA12	TA16	TA17	US1	US2	US3	US4
MSP430F2001	C	✓	✓	✓	✓	✓	✓	✓				✓	✓					
	B	✓	✓	✓	✓	✓	✓	✓				✓	✓					
	A	✓	✓	✓	✓	✓	✓	✓	✓			✓	✓	✓				
MSP430F2011	C	✓	✓	✓	✓	✓	✓	✓				✓	✓					
	B	✓	✓	✓	✓	✓	✓	✓				✓	✓					
	A	✓	✓	✓	✓	✓	✓	✓	✓			✓	✓	✓				
MSP430F2002	C	✓	✓	✓	✓	✓	✓	✓				✓	✓					✓
	B	✓	✓	✓	✓	✓	✓	✓				✓	✓					✓
	A	✓	✓	✓	✓	✓	✓	✓	✓			✓	✓					✓
MSP430F2012	C	✓	✓	✓	✓	✓	✓	✓				✓	✓					✓
	B	✓	✓	✓	✓	✓	✓	✓				✓	✓					✓
	A	✓	✓	✓	✓	✓	✓	✓	✓			✓	✓					✓
MSP430F2003	D	✓	✓	✓	✓	✓	✓	✓			✓	✓	✓					✓
	C	✓	✓	✓	✓	✓	✓	✓			✓	✓	✓					✓
	B	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F2013	D	✓	✓	✓	✓	✓	✓	✓			✓	✓	✓					✓
	C	✓	✓	✓	✓	✓	✓	✓			✓	✓	✓					✓
	B	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓

Detailed Bug Description

SBW1 SBW1 - Bug description:

Module: Spy Bi-Wire-Interface

An error in the Spy Bi-Wire-Interface will increase the ICC under normal operating conditions.

Workaround:
None

SDA2 SDA2 - Bug description:

Module: SD16_A, Internal reference generator is out of spec

The SD16_A reference generator may not meet the maximum temperature coefficient specification of 50 ppm/K.

Workaround:
The SD16_A internal reference can be adjusted to operate within the specification by writing 0x61 to memory location 0xBF. This will correct the temperature coefficient of the internal reference and center the typical voltage to 1.20V.

Detailed Bug Description (continued)

TA17 TA17 - Bug description:

Module: TimerA, Function: Capture Input CCI0B missing ACLK connection

The TimerA Capture Input CCI0B is not internally connected to the ACLK signal.

Workaround:

The ACLK signal can be output on P1.0 and externally input on a TimerA capture input pin.

USI1 USI1 - Bug description:

Module: USI, Function: USICKCTL cannot be written

When the USI is in active operation mode i.e. when USICNT \neq 0, the USICKCTL cannot be written. If written, the USICNT is cleared and the USIIFG is set. Operation using the USISWCLK is not possible.

Workaround:

None

USI2 USI2 - Bug description:

Module: USI, Function: I2C Slave mode erroneously pulls SCL low

When the USI is configured in I2C slave mode, SCL will incorrectly be pulled low when USICNTx is written with a value of 1.

Workaround:

None

USI3 USI3 - Bug description:

Module: USI, Function: I2C Slave mode does not hold SCL low

When the USI is configured in I2C slave mode, the module does not hold SCL low while USISTTIFG = 1 following a start condition.

Workaround:

None

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

TI products are not authorized for use in safety-critical applications (such as life support) where a failure of the TI product would reasonably be expected to cause severe personal injury or death, unless officers of the parties have executed an agreement specifically governing such use. Buyers represent that they have all necessary expertise in the safety and regulatory ramifications of their applications, and acknowledge and agree that they are solely responsible for all legal, regulatory and safety-related requirements concerning their products and any use of TI products in such safety-critical applications, notwithstanding any applications-related information or support that may be provided by TI. Further, Buyers must fully indemnify TI and its representatives against any damages arising out of the use of TI products in such safety-critical applications.

TI products are neither designed nor intended for use in military/aerospace applications or environments unless the TI products are specifically designated by TI as military-grade or "enhanced plastic." Only products designated by TI as military-grade meet military specifications. Buyers acknowledge and agree that any such use of TI products which TI has not designated as military-grade is solely at the Buyer's risk, and that they are solely responsible for compliance with all legal and regulatory requirements in connection with such use.

TI products are neither designed nor intended for use in automotive applications or environments unless the specific TI products are designated by TI as compliant with ISO/TS 16949 requirements. Buyers acknowledge and agree that, if they use any non-designated products in automotive applications, TI will not be responsible for any failure to meet such requirements.

Following are URLs where you can obtain information on other Texas Instruments products and application solutions:

Products

Amplifiers	amplifier.ti.com
Data Converters	dataconverter.ti.com
DSP	dsp.ti.com
Interface	interface.ti.com
Logic	logic.ti.com
Power Mgmt	power.ti.com
Microcontrollers	microcontroller.ti.com
RFID	www.ti-rfid.com
Low Power Wireless	www.ti.com/lpw

Applications

Audio	www.ti.com/audio
Automotive	www.ti.com/automotive
Broadband	www.ti.com/broadband
Digital Control	www.ti.com/digitalcontrol
Military	www.ti.com/military
Optical Networking	www.ti.com/opticalnetwork
Security	www.ti.com/security
Telephony	www.ti.com/telephony
Video & Imaging	www.ti.com/video
Wireless	www.ti.com/wireless

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265
Copyright © 2007, Texas Instruments Incorporated